

19" Patch panel 50xRJ45/u, Cat.3

P/N: 509020







2.



Strip approximately 75 mm of the cable jacket.

3.





Use the LSA impact tool to punch and con- Use the cable tie to manage these cables, nect the wires on the IDC.



then complete the installation.